

PF Opaque Base 3000

General

A special transparent viscose base used for anti-skid application under socks and carpets.

Advantages

- It is phthalate free. It is fixed at (320°F /160°C), 1,5 – 2 mins.
- PF Opaque Base 3000 has elastic and opaque cover effect.

Applications

- PF Opaque Base 3000 is applied for obtain to opaque cover transparent effect.
- After using, the screen should be cleaned with the synthetic thinner.
- It provides dropped and non-slipped property to sock base.

Usage

- It provides to print with the silk-screen that are made between 32-77 mesh.
- 60 - 80 Shore, U type dr. blade should be used.

Storage & Shelf Life

- Keep containers dry and tightly closed. Store in a ventilated place between (+5)-(+30)°C /(+41)-(+86)°F of temperature.
- It should be consumed within 2 years after the production date.

Technical Details



Appearance
Paste-sober



Odor
Characteristic



Color
Transparent



Viscosity
[(25 °C) sp: 93, rpm: 2 Brookfield] :
200.000 – 250.000 [mPa.s]



Density
1,1 g/cm³ (77 °F/25°C)



pH
N/A



Boiling Point
>100 °C (212 °F)



Solubility
N/A



Explosion Hazard
It is not explosive



Packaging Information
PF Opaque Base 3000 is packed in
10/20/25 kg cans

Important

The technical application and information that have been given above, are designed only as using instructions. Should not be considered as a warranty for any other use. When any help or assistance is required, our technical department is ready for help.

In case of emergency, Safety Data Sheet of this product should be ready for help at the working area. The warnings are given on safety data sheet of this product is for use outside the manufacturer/ distributor to direct/indirect can not be held responsible for any loss or damage.